

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| | | | | | | | | Landers | |
|---|--|------------------------------|---|---|-----------------------|-------|--------|-----------------------------|------|
| Intersection ID: 7035 | Main Street: OLD_MT_HOLLY_RD | | | Cross Street: WINDY_VALLEY_DR | | | | Location: | S |
| ADA ID: BE58F79C29D9 | Ramp Type: Perp | | | Initial Pass/Fail: Fail Overall Compliance: | | | nce: N | o Severity Score: | 8.75 |
| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | | | | | |
| the second se | N MALINE | Possible Solutions: | | Comp | liance Description | Data | Comp | liance Description | Data |
| | V. STAT | Remove & Replace Entire Ramp | | N/A | Ramp Length (in) | 72.0 | Yes | Ramp Slope (%) | 7.0 |
| The Same Color and | the hade ? | | | No | Ramp Width (in) | 46.5 | Yes | Ramp XSlope (%) | 1.9 |
| | | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| and the second second | 1 Danie | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| A the set of the set | L'a z | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | All a | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| S GR WINDER THE GIO | a la | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| the second se | | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| 01 July 24 14 | OF THE | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| La Charles and Charles | Alle | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | 1000 | | | N/A | Shared Landing? | N/A | | | |
| | A MAK | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | 10-36 | Not Found, R304.5.1 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | | | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| A PARTE A | S. Ber | | | | X Walk 1 Direction | To NW | | X Walk 2 Direction | N/A |
| | | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name OLD | MT HOLLY RD | | | | X Walk 1 Slope (%) | 6.0 | | X Walk 2 Slope (%) | N/A |
| Stop Condition-Street 2 | None | | | | X Walk 1 X Slope (%) | 2.8 | | X Walk 2 X Slope (%) | N/A |
| Street 2 Name | N/A | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | N/A | | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: \$ | 1850.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | N/A | | | N/A |

Yes Surface Condition? (G/P)

Good

