cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 53122 Main Street: CROCKETT_PARK_PL					Cross Street: IVERSON_WY					Location:	
ADA ID: BF8915F9030F	A ID: BF8915F9030F Ramp Type: Combination2Diag				ial Pass/Fail: Fail Overall Comp			omplian	ance: No Severity Score:		0
Codes/Mitigation Info/Possible Solution Field Measurements/Component Co										nent Compliance	
	Possible Solutions:				iance Description		Data Cor		liance Description	Data	
	1 2 8 6 0 M	Remove & Replace Curb	urb Ramp With		N/A	Ramp Length	LT (in)	44.0	N/A	Ramp Length RT (in)	N/A
	2 · · · · ·	Two New Directional Rai			No	Ramp Width L		46.0	N/A	Ramp Width RT (in)	N/A
		Equivalent.			No	Ramp Slope L	_T (%)	10.1	N/A	Ramp Slope RT (%)	N/A
					No	Ramp XSlope	e LT (%)	3.6	N/A	Ramp XSlope RT (%)	N/A
20 1 1 1 1 1 1 1	110				N/A	Ramp Length	(in)	26.5	No	Ramp Slope (%)	10.7
	JE MAX				Yes	Ramp Width ((in)	48.0	No	Ramp XSlope (%)	6.4
and the second second		Surveyor Notes:			N/A	Flare Type LT	-	N/A	N/A	Flare Type RT	N/A
	1 12 1	N/A			N/A	Flare Slope L	T (%)	N/A	N/A	Flare Slope RT (%)	N/A
A CONTRACTOR	2 10/2 32				N/A	Flare Traversa	able LT?	N/A	N/A	Flare Traversable RT?	N/A
- TOP 4	A 6.				N/A	Landing Leng	th (in)	N/A	N/A	DWS Provided?	N/A
THE PLUE					N/A	Landing Width	h (in)	N/A	N/A	DWS Contrast?	N/A
QIO ONE		PROW/ADA:			N/A	Landing Slope	e (%)	N/A	N/A	DWS Length (in)	N/A
Not Found, R304.5.1, R304.2.2,					N/A	Landing X Slo	ope (%)	N/A	N/A	DWS Full Width?	N/A
		R304.5.3, R304.3.2			N/A	Landing Curb	? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A single the	E T G				N/A	Shared Landii	ng?	N/A			
No.					N/A	Gutter Pondir	וg?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	None				N/A	Gutter Lip Ht	(in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	IVERSON WY				N/A	Painted X Wa	lk1?	No	N/A	Painted X Walk2?	No
Street 2 Name	StopSign					X Walk 1 Dire	ection	To SW		X Walk 2 Direction	To SE
Stop Condition-Street 2 CROCKETT PARK PL						X Walk 1 Widt	th (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slop	be (%)	0.9		X Walk 2 Slope (%)	3.5
						X Walk 1 X Sl	ope (%)	5.1		X Walk 2 X Slope (%)	3.0
		Total Cost:	\$	3200.00	N/A	Ramp inside)	XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	5.0		Clear Space?	N/A
						Road X Slope	e (%)	1.0	N/A	Clear Space to XWalk (in)	N/A
		CTOD	1	Lab.	1	and a product			N/A	Any Obstruction?	N/A
	Marine Bassille					Sea DET.	Ţ			Obstruction Type	
											N/A
ALL CHARGE AREA									N/A	Storm Grate/Utility Hazard?	N/A
			C. Married C.							Storm Grate/Utility Type	
						Contraction of the local division of the loc					N/A
					T				Yes	Surface Condition? (G/P)	Good
	1-1-1			T	-					Curb Slope (%)	17.5