## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 49894 Mai	n Street: ROCKY_FORD_CLUB_RD	Cross Street: RUTH_FERRELL_CT				Location:	NE
ADA ID: BFCF10998600 Ran	CF10998600 Ramp Type: Perp			Initial Pass/Fail: Pass Overall Compliance: No			7.75
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
	Possible Solutions:	Com	Compliance Description Data Compliance Description				Data
	Remove & Replace Entire Ramp	. N/A	Ramp Length (in)	72.0	Yes	Ramp Slope (%)	6.4
	Remove & Replace Gutter.	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.2
		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	6.8	Yes	Flare Slope RT (%)	9.5
		N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
		Yes	Landing Length (in)	48.0	Yes	DWS Provided?	Yes
	Surveyor Notes:	Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes
	N/A	Yes	Landing Slope (%)	1.5	Yes	DWS Length (in)	24.5
		Yes	Landing X Slope (%)	0.8	Yes	DWS Full Width?	Yes
	and the second se	N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	5.5
		N/A	Shared Landing?	No			
	PROW/ADA:	Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.4
	Not Found, R304.5.3, R305.2,	No	Gutter Lip Ht (in)	0.5	No	Gutter X Slope (%)	2.2
	R302.7.2	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
			X Walk 1 Direction	To W		X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name ROCKY FORD CLUB	RD		X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 N	one		X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A		Road Slope (%)	N/A	N/A	Clear Space?	Yes
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Total Cost: \$	2600.00	Obstruction Type			Storm Grate/Utility Type	
				N/A			N/A

Yes Surface Condition? (G/P) Good

