cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 23527	ntersection ID: 23527 Main Street: BRANDON_FOREST_DR			Cross Street: HAMLIN_PARK_DR				Location:	SW
ADA ID: C06591D887E	E Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp V	Nith	N/A	Ramp Length (in)	80.0	No	Ramp Slope (%)	10.1
8 3838 1		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.7
SI COMMENT	A BAR STATE	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	HANLIN PARK DR			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
All Allers				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
CAR CA		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
OCE		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A SERV				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
3 STOD	E C			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A CONTRACTOR				N/A	Shared Landing?	N/A			
	A Start	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	· NOTE	R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
					X Walk 1 Direction	To E		X Walk 2 Direction	To N
				N/A	X Walk 1 Width (in)	108.0	N/A	X Walk 2 Width (in)	96.0
Street 1 Name	BRANDON FOREST DR	•			X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	0.5
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.5		X Walk 2 X Slope (%)	0.4
Street 2 Name	HAMLIN PARK DR			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes
Stop Condition-Street 1	StopSign				Road Slope (%)	1.4	N/A	Clear Space?	N/A
,					Road X Slope (%)	0.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	0.0 N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
		· · · · · · · · · · · · · · · · ·				N/A			N/A
						IN/A			IN/A

The Party States of the second second