

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

9.4

1.8

N/A

Good

Intersection ID: 4764 Main Street: ELDERBANK DR **Cross Street: TRINITY RD** Location: SW Initial Pass/Fail: Fail **Overall Compliance: No** 30 ADA ID: C0E115A8A731 Ramp Type: Perp **Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

58.5

33.0

N/A

1.3

No

To N

N/A

3.1

0.9

N/A

N/A

N/A

N/A

N/A

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?



ELDERBANK DR Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A

COCIDIO COIGNION		i iola ilio
Possible Solutions:	Compl	iance Description
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)
·	No	Ramp Width (in)
	N/A	Flare Type LT
	N/A	Flare Slope LT (%)
	N/A	Flare Traversable LT
	N/A	Landing Length (in)
Surveyor Notes:	N/A	Landing Width (in)
N/A	N/A	Landing Slope (%)
	N/A	Landing X Slope (%)
	N/A	Landing Curb? (Y/N)
	N/A	Shared Landing?
PROW/ADA:	N/A	Gutter Ponding?
R304.5.1, R304.2.2	N/A	Gutter Lip Ht (in)
	N/A	Painted X Walk1?
		X Walk 1 Direction
	N/A	X Walk 1 Width (in)
		X Walk 1 Slope (%)
		X Walk 1 X Slope (%
	N/A	Ramp inside XWalk1
		Road Slope (%)

Curveyor Notes.			11/7
N/A			N/A
			N/A
			N/A
			N/A
PROW/ADA:			N/A
R304.5.1, R304.2.2			N/A
			N/A
			N/A
			N/A
Total Cost:	\$	1850.00	N/A
Total Cost.	Ψ	1030.00	







