

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 43116	Main Street: CENTRAL_AV			Cross Street: PECAN_AV				Location:	SW
ADA ID: C19B0BC73F66	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	21.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
900)	25. 9	Possible Solutions:					Compliance Description		Data
		Remove & Replace Entire F	Ramp.	N/A	Ramp Length (in)	66.0	No	Ramp Slope (%)	8.4
	14 1		•	No	Ramp Width (in)	46.0	Yes	Ramp XSlope (%)	1.7
	Then I			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	State .			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
G. C.	(0.00			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
GENUKAL		e01		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	1 10	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	E Hart			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	Can Ball	λ.		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	NOT THE			N/A	Shared Landing?	N/A			
	at the set	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304	1.2.2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
and the second				X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
Action of the second se				N/A	X Walk 1 Width (in)	144.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	PECAN AV				X Walk 1 Slope (%)	4.4		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1850.	00	Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

