## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

6.7

Main Street: E_WOODLAWN_RD		Cross	Cross Street: MURRAYHILL_RD			Location: N				
Ramp Type: ParaDiag		Initial	Initial Pass/Fail: Fail Overall Com			iance: No Severity Score: 13.7		13.75		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
Possible Solution			Compliance Description			Data Compliance Description			Data	
	Remove & Replace Curt	o Ram	p With	N/A	Ramp Length LT (in)	52.0	N/A	Ramp Length RT (in)	49.0	
11	-		•	Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	62.0	
1 million	Equivalent.		Yes	Ramp Slope LT (%)	5.3	No	Ramp Slope RT (%)	8.7		
1 2				No	Ramp XSlope LT (%)	2.2	No	Ramp XSlope RT (%)	3.3	
		8		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
				N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
A A A				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
the state of the second s				N/A	Shared Landing?	N/A				
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
AL RD	PROW/ADA:			N/A	Gutter Lip Ht (in)	1.0	N/A	Gutter X Slope (%)	N/A	
	R304.5.3. R304.3.2			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
					X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
00				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
					X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	1.2	
ODLAWN RD					X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	0.8	
None				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
RRAYHILL RD					Road Slope (%)	1.2	N/A	Clear Space?	N/A	
StopSign					Road X Slope (%)	0.0	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
					Obstruction Type			Storm Grate/Utility Type		
	Total Cost:	\$	3200.00			N/A			N/A	
							Yes	Surface Condition? (G/P)	Good	
	Ramp Ty tigation Info	Ramp Type: ParaDiag     tigation Info/Possible Solution     Possible Solutions:     Remove & Replace Curl two New Directional Ra Equivalent.     Surveyor Notes:     N/A     PROW/ADA:     RayHilLL RD StopSign	Ramp Type: ParaDiag     tigation Info/Possible Solution     Possible Solutions:     Remove & Replace Curb Ram Two New Directional Ramps of Equivalent.     Surveyor Notes:     N/A     PROW/ADA:     RayHilLL RD StopSign	Ramp Type:   ParaDiag   Initial     tigation Info/Possible Solution   Initial     Stigation Info/Possible Solutions:   Possible Solutions:     Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.   Surveyor Notes:     N/A   PROW/ADA:     ODLAWN RD None   Radultation StopSign	Ramp Type:   ParaDiag   Initial Pass/Fi     tigation Info/Possible Solutions:   Comp     Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.   N/A     Yes   Yes     Surveyor Notes:   N/A     N/A   N/A     PROW/ADA:   N/A     R304.5.3, R304.3.2   N/A     N/A   N/A     N/A   N/A     N/A   N/A     N/A   N/A     N/A   N/A	Ramp Type:   ParaDiag   Initial Pass/Fail:   Fail   Overall     tigation Info/Possible Solution   Field Measur     Possible Solutions:   Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.   N/A   Ramp Length LT (in)   Yes   Ramp Width LT (in)     Yes   Ramp Slope LT (%)   N/A   Landing Uength (in)   N/A   Landing Vidth (in)     Surveyor Notes:   N/A   Landing Slope (%)   N/A   Landing Slope (%)   N/A     N/A   Randing Curb? (Y/N)   N/A   Landing Curb? (Y/N)   N/A   Started Landing?     N/A   Radot S.3, R304.3.2   N/A   Gutter Ponding?   N/A   Walk 12'     ODLAWN RD   None   Ramp Inside XWalk1?   KWalk 1 Slope (%)   X/A   XWalk 1 Slope (%)     N/A   Ramp Inside XWalk1?   Road Slope (%)   N/A   Ramp Inside XWalk1?     StopSign   N/A   Ramp Inside XWalk1?   Road Slope (%)   N/A	Ramp Type:   ParaDiag   Initial Pass/Fail:   Fail   Overall Compliant     tigation Info/Possible Solution   Field Measurements/C     Possible Solutions:   Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.   Compliance Description   Data     N/A   Ramp Kide LT (in)   52.0     Yes   Ramp Width LT (in)   60.0     Yes   Ramp Slope LT (%)   5.3     No   Ramp XSlope LT (%)   2.2     N/A   Landing Length (in)   N/A     Surveyor Notes:   N/A   Landing Slope (%)   N/A     N/A   Landing Slope (%)   N/A   N/A   Slope (%)   N/A     N/A   Surveyor Notes:   N/A   Landing Curb? (Y/N)   N/A     N/A   Landing Curb? (Y/N)   N/A   N/A   Slope (%)   N/A     N/A   Stop Slop   N/A   Gutter Ponding?   N/A     N/A   N/A   Gutter Lip Ht (in)   1.0     N/A   N/A   Slope (%)   0.1     None   N/A   Kathi?   No     Radot.5.3, R304.3.2   N/A   Rathi X Valk 1 Note(%) <t< td=""><td>Ramp Type:   ParaDiag   Initial Pass/Fail:   Fail   Overall Compliance:   N/     tigation Info/Possible Solution:   Field Measurements/Compo   Data   Comp     Possible Solutions:   Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.   N/A   Ramp Length LT (in)   \$2.0   N/A     N/A   Ramp Slope LT (%)   5.3   No   No   Ramp XSlope LT (%)   5.3   No     Surveyor Notes:   N/A   Landing Vield (in)   N/A   N/A   N/A   N/A     N/A   Landing Vield (in)   N/A   N/A   N/A   N/A     Surveyor Notes:   N/A   N/A   Landing Curb? (Y/N)   N/A   N/A     N/A   Landing Curb? (Y/N)   N/A   N/A   N/A   N/A     N/A   Gutter IpH (in)   1.0   N/A     N/A   Landing Curb? (Y/N)   N/A   N/A     N/A   Gutter IpH (in)   1.0   N/A     N/A   Gutter IpH (in)   1.0   N/A     None   None   N/A   Stops(%)   0.1     None   None   N/A   Road X Slop</td><td>Ramp Type: ParaDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score:   tigation Info/Possible Solution: Field Measurements/Component Compliance Compliance Description Data Compliance Description   Possible Solutions: Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent. N/A Ramp Length LT (in) 52.0 N/A Ramp Length RT (in)   Yees Ramp Slope LT (%) 5.3 No Ramp Slope RT (%) 2.2 No Ramp Slope RT (%)   Surveyor Notes: N/A Landing Slope (%) N/A N/A DWS Provided?   N/A Landing Curb? (Y/N) N/A N/A DWS Contrast?   N/A Landing Curb? (Y/N) N/A N/A Gutter Slope (%)   N/A Gutter Ponding? N/A N/A Gutter Slope (%)   N/A R304.5.3, R304.3.2 N/A Gutter Ponding? N/A X/A</td></t<>	Ramp Type:   ParaDiag   Initial Pass/Fail:   Fail   Overall Compliance:   N/     tigation Info/Possible Solution:   Field Measurements/Compo   Data   Comp     Possible Solutions:   Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.   N/A   Ramp Length LT (in)   \$2.0   N/A     N/A   Ramp Slope LT (%)   5.3   No   No   Ramp XSlope LT (%)   5.3   No     Surveyor Notes:   N/A   Landing Vield (in)   N/A   N/A   N/A   N/A     N/A   Landing Vield (in)   N/A   N/A   N/A   N/A     Surveyor Notes:   N/A   N/A   Landing Curb? (Y/N)   N/A   N/A     N/A   Landing Curb? (Y/N)   N/A   N/A   N/A   N/A     N/A   Gutter IpH (in)   1.0   N/A     N/A   Landing Curb? (Y/N)   N/A   N/A     N/A   Gutter IpH (in)   1.0   N/A     N/A   Gutter IpH (in)   1.0   N/A     None   None   N/A   Stops(%)   0.1     None   None   N/A   Road X Slop	Ramp Type: ParaDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score:   tigation Info/Possible Solution: Field Measurements/Component Compliance Compliance Description Data Compliance Description   Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. N/A Ramp Length LT (in) 52.0 N/A Ramp Length RT (in)   Yees Ramp Slope LT (%) 5.3 No Ramp Slope RT (%) 2.2 No Ramp Slope RT (%)   Surveyor Notes: N/A Landing Slope (%) N/A N/A DWS Provided?   N/A Landing Curb? (Y/N) N/A N/A DWS Contrast?   N/A Landing Curb? (Y/N) N/A N/A Gutter Slope (%)   N/A Gutter Ponding? N/A N/A Gutter Slope (%)   N/A R304.5.3, R304.3.2 N/A Gutter Ponding? N/A X/A	

