


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | | |
|-----------------------|-------------------------------|----------------------------|------------------------|----------------------|
| Intersection ID: 2942 | Main Street: ASBURY_CHAPEL_RD | Cross Street: EASTFIELD_RD | Location: | E |
| ADA ID: C2239CDC7C31 | Ramp Type: Perp | Initial Pass/Fail: Fail | Overall Compliance: No | Severity Score: 12.5 |

| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | | | | |
|--|-------------------------------|------------|---|-----------------------|-------|------------|-----------------------------|------|
|  | Possible Solutions: | | Compliance | Description | Data | Compliance | Description | Data |
| | Remove & Replace Entire Ramp. | | N/A | Ramp Length (in) | 60.0 | No | Ramp Slope (%) | 10.0 |
| | | | Yes | Ramp Width (in) | 56.5 | Yes | Ramp XSlope (%) | 1.6 |
| | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| Surveyor Notes: | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| N/A | | | N/A | Shared Landing? | N/A | | | |
| PROW/ADA: | | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| Not Found, R304.2.2 | | | N/A | Gutter Lip Ht (in) | 1.0 | N/A | Gutter X Slope (%) | N/A |
| | | | N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | N/A |
| | | | | X Walk 1 Direction | To SW | | X Walk 2 Direction | N/A |
| | | | N/A | X Walk 1 Width (in) | 113.0 | N/A | X Walk 2 Width (in) | N/A |
| | | | | X Walk 1 Slope (%) | 0.8 | | X Walk 2 Slope (%) | N/A |
| | | | | X Walk 1 X Slope (%) | 4.5 | | X Walk 2 X Slope (%) | N/A |
| | | | N/A | Ramp inside XWalk1? | Yes | N/A | Ramp inside XWalk2? | N/A |
| | | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | N/A | | | N/A |
| | | | | | | Yes | Surface Condition? (G/P) | Good |
| Total Cost: | | \$ 1850.00 | | | | | | |

