

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30360 Main Street: TIMBERTOP_LN Cross Street: WORLEY_DR Location: SW

ADA ID: C285CEBF284F Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 46.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

WORLEY DR StopSign TIMBERTOP LN None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.1, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

Field Measurements/Component Compliance							
	Compliance Description		Data	Compliance Description		Description	Data
	N/A	Ramp Length (in)	45.5	No	Ramp	Slope (%)	11.6
	No	Ramp Width (in)	47.5	No	Ramp	XSlope (%)	9.4
	N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutte	Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	No
		X Walk 1 Direction	To SE		X Wal	k 2 Direction	To NE
	N/A	X Walk 1 Width (in)	N/A	N/A	X Wal	k 2 Width (in)	N/A
		X Walk 1 Slope (%)	6.0		X Wal	k 2 Slope (%)	2.1
		X Walk 1 X Slope (%)	4.0		X Wal	k 2 X Slope (%)	9.6
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
		Road Slope (%)	10.8	N/A	Clear	Space?	N/A
		Road X Slope (%)	1.6	N/A	Clear	Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
		Obstruction Type			Storm	Grate/Utility Type	
			N/A				N/A
				Yes	Surfac	ce Condition? (G/P)	Good
-							





