

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11747Main Street: W_10TH_STCross Street: N_TRYON_STLocation: WADA ID: C36D3328EA5FRamp Type: PerpDiagInitial Pass/Fail: Fail Overall Compliance: No Severity Score: 10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

N TRYON ST None W 10TH ST StopSign Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Fleid Measurements/Component Compliance							
	Comp	Compliance Description		Compliance Description		Description	Data
	N/A	Ramp Length (in)	67.0	Yes	Ramp	Slope (%)	5.6
	No	Ramp Width (in)	38.0	No	Ramp	XSlope (%)	4.2
	N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	No
		X Walk 1 Direction	To SE		X Wa	lk 2 Direction	To NE
	N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
		X Walk 1 Slope (%)	0.5		X Wa	lk 2 Slope (%)	1.3
		X Walk 1 X Slope (%)	3.4		X Wa	lk 2 X Slope (%)	0.4
	N/A	Ramp inside XWalk1?	N/A	N/A	Ram	inside XWalk2?	N/A
		Road Slope (%)	0.3	N/A	Clear	Space?	N/A
		Road X Slope (%)	5.1	N/A	Clear	Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
				1	_		

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

Good







Obstruction Type