## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10040083	Main Str	Main Street: TUCKASEEGEE_RD			N/A	Location:	N		
ADA ID: C4933619B16A	Ramp Ty	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No				12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	19 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Possible Solutions:		Comp	bliance Description	cription Data Compliance		liance Description	Data
		Remove & Replace Entire Ra	mp.	N/A	Ramp Length (in)	72.0	N/A	Grade Break?	N/A
X	The second second		P.	Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0
	A ANA			No	Ramp Slope (%)	8.4	N/A	Grade Break XSlope (%)	0.0
	MAL MAN			Yes	Ramp XSlope (%)	0.5			
* A A A A A A A A A A A A A A A A A A A	NAME:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	12 14			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
The second secon		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Thomas to	and I have	PONDING ON RAMP		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
EBEERANDO				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
C. C.	State State N			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
1 Variable and 1	Part and a	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
E E TANA		R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
A CALLER A	PP- SHARE			N/A	Gutter Ponding?	Yes	N/A	Gutter Slope (%)	N/A
	SIV OF			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
mucho - all of the second				N/A	Painted X Walk1?	No		Road Slope (%)	9.9
Street 1 Name T	UCKASEEGEE RD				X Walk 1 Direction	To S		Road X Slope (%)	0.1
Stop Condition-Street 1	None				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	9.9	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	0.1	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	28.4

