

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

13.6

1.1

N/A

Good

Main Street: PAMPLIN CT Cross Street: N/A Intersection ID: N/A Location: SE Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: C4F83ADFCB64 Ramp Type: Perp Severity Score: 33.75

Codes/Mitigation Info

Field Measurements/Component Compliance

No

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

93.0

46.5

N/A

No

N/A

2.8

1.4

N/A

N/A

N/A

N/A

N/A

To NW

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?



PAMPLIN CT Street 1 Name Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A

/Possible Solution		Field Me
Possible Solutions:	Comp	liance Description
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)
· ·	No	Ramp Width (in)
	N/A	Flare Type LT
	N/A	Flare Slope LT (%)
	N/A	Flare Traversable LT
	N/A	Landing Length (in)
Surveyor Notes:	N/A	Landing Width (in)
N/A	N/A	Landing Slope (%)
	N/A	Landing X Slope (%
	N/A	Landing Curb? (Y/N
	N/A	Shared Landing?
PROW/ADA:	N/A	Gutter Ponding?
Not Found, R304.5.1, R304.2.2	N/A	Gutter Lip Ht (in)
	N/A	Painted X Walk1?
		X Walk 1 Direction
	N/A	X Walk 1 Width (in)
		X Walk 1 Slope (%)
		X Walk 1 X Slope (%
	N/A	Ramp inside XWalk
		Road Slope (%)
		Road X Slone (%)

N/A				11//
				N/A
				N/A
				N/A
PROW/ADA:				N/A
Not Found,	R304.5.1, R304	.2.2		N/A
·	·			N/A
				N/A
				N/A
Total Cost:		\$	1850.00	N/A

P III		



