

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18716 Main Street: COLONY_RD Cross Street: RUNNYMEDE_LN Location: NW **Overall Compliance: No** ADA ID: C501DE68964E Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 10

Codes/Mitigation Info/Possible Solution



COLONY RD Street 1 Name Signal Stop Condition-Street 2 Street 2 Name N/A Stop Condition-Street 1 N/A

| Possible Solutions: | 9 | | |
|-------------------------------|---|--|--|
| Remove & Replace Entire Ramp. | | | |
| | N | | |
| | N | | |
| | 1 | | |
| | 1 | | |
| | 1 | | |
| Surveyor Notes: | 1 | | |
| N/A | 1 | | |
| | 1 | | |
| | 1 | | |
| | 1 | | |
| PROW/ADA: | 1 | | |
| Not Found, R304.5.1 | N | | |
| | N | | |
| | | | |
| | N | | |
| | | | |
| | | | |

Total Cost:



1850.00

| Field Measurements/Component Compliance | | | | | | | | |
|---|-----------------------|-------|------|--------|-------------------------|------|--|--|
| Comp | liance Description | Data | Comp | liance | Description | Data | | |
| N/A | Ramp Length (in) | 83.0 | Yes | Ramp | Slope (%) | 6.4 | | |
| No | Ramp Width (in) | 40.5 | Yes | Ramp | XSlope (%) | 2.2 | | |
| N/A | Flare Type LT | N/A | N/A | Flare | Type RT | N/A | | |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare | Slope RT (%) | N/A | | |
| N/A | Flare Traversable LT? | N/A | N/A | Flare | Traversable RT? | N/A | | |
| N/A | Landing Length (in) | N/A | N/A | DWS | Provided? | N/A | | |
| N/A | Landing Width (in) | N/A | N/A | DWS | Contrast? | N/A | | |
| N/A | Landing Slope (%) | N/A | N/A | DWS | Length (in) | N/A | | |
| N/A | Landing X Slope (%) | N/A | N/A | DWS | Full Width? | N/A | | |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS | Offset (in) | N/A | | |
| N/A | Shared Landing? | N/A | | | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutte | r Slope (%) | N/A | | |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutte | r X Slope (%) | N/A | | |
| N/A | Painted X Walk1? | Yes | N/A | Paint | ed X Walk2? | N/A | | |
| | X Walk 1 Direction | To NE | | X Wa | lk 2 Direction | N/A | | |
| N/A | X Walk 1 Width (in) | 115.0 | N/A | X Wa | lk 2 Width (in) | N/A | | |
| | X Walk 1 Slope (%) | 6.5 | | X Wa | lk 2 Slope (%) | N/A | | |
| | X Walk 1 X Slope (%) | 4.8 | | X Wa | lk 2 X Slope (%) | N/A | | |
| N/A | Ramp inside XWalk1? | Yes | N/A | Ram | inside XWalk2? | N/A | | |
| | Road Slope (%) | N/A | N/A | Clear | Space? | N/A | | |
| | Road X Slope (%) | N/A | N/A | Clear | Space to XWalk (in) | N/A | | |
| N/A | Any Obstructions? | N/A | N/A | Storn | n Grate/Utility Hazard? | N/A | | |
| | Obstruction Type | | | Storn | n Grate/Utility Type | | | |
| | | N/A | | | | N/A | | |
| | | | Yes | Surfa | ce Condition? (G/P) | Good | | |
| | Wind Commission | | | | | | | |

