

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

9.0

1.1

N/A

Good

Intersection ID: 50619 Main Street: COTTON GUM RD Cross Street: YELLOW OAK RD Location: SE **Overall Compliance: No** 12.5 **ADA ID: C70667D39ADA** Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

No

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

47.0

48.0

N/A

No

To W

N/A

2.8

3.2

N/A

N/A

N/A

N/A

N/A

Flare Slope LT (%) Flare Traversable LT?

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road X Slope (%)

Any Obstructions?

**Obstruction Type** 



**COTTON GUM RD** Street 1 Name Stop Condition-Street 2 None N/A Street 2 Name N/A

<u>,,</u>	i ossible solution		i ieiu ivie
7	Possible Solutions:	Compliance Description	
The state of	Remove & Replace Entire Ramp.	N/A	Ramp Length (in)
1	·	Yes	Ramp Width (in)
-		N/A	Flare Type LT
		N/A	Flare Slope LT (%)
I		N/A	Flare Traversable LT
ļ		N/A	Landing Length (in)
1	Surveyor Notes:	N/A	Landing Width (in)
	N/A	N/A	Landing Slope (%)
		N/A	Landing X Slope (%
		N/A	Landing Curb? (Y/N
e G		N/A	Shared Landing?
d	PROW/ADA:	N/A	Gutter Ponding?
	Not Found, R304.2.2	N/A	Gutter Lip Ht (in)
å		N/A	Painted X Walk1?
3			X Walk 1 Direction
•		N/A	X Walk 1 Width (in)
			X Walk 1 Slope (%)
			X Walk 1 X Slope (%
		N/A	Ramp inside XWalk
			Road Slope (%)



Total Cost:



N/A

1850.00

