

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

2.7

5.3

Intersection ID: 10041631Main Street: WHITEHALL\_PARK\_DRCross Street: N/ALocation:NEADA ID: C80AED1FB0F2Ramp Type: BlendTrans2Initial Pass/Fail: FailOverall Compliance: NoSeverity Score: 12.5

Compliance Description

Ramp Length (in)

Ramp Width (in)

N/A

Yes

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

60.0 No

Yes


Data

69.0

Compliance Description

BlendTrans Slope (%)

BlendTrans XSlope (%)



Street 1 Name
Stop Condition-Street 1
Street 2 Name
WHITEHALL PARK DR
None
N/A

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

R304.5.3

N/A None

Total Cost: \$ 3200.00

N/A	Flare Type RT	N/A	N/A	Flare Type LT	N/A
N/A	Flare Slope RT (%)	N/A	N/A	Flare Slope LT (%)	N/A
N/A	Flare Traversable RT?	N/A	N/A	Flare Traversable LT?	N/A
N/A	DWS Provided?	N/A	N/A	Landing Length (in)	N/A
N/A	DWS Contrast?	N/A	N/A	Landing Width (in)	N/A
N/A	DWS Length (in)	N/A	N/A	Landing Slope (%)	N/A
N/A	DWS Full Width?	N/A	N/A	Landing X Slope (%)	N/A
N/A	DWS Offset (in)	N/A	N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
N/A	Gutter Slope (%)	N/A	N/A	Gutter Ponding?	N/A
N/A	Gutter X Slope (%)	N/A	N/A	Gutter Lip Ht (in)	N/A
No	Painted X Walk2?	N/A	No	Painted X Walk1?	N/A
To SE	X Walk 2 Direction		To SW	X Walk 1 Direction	
N/A	X Walk 2 Width (in)		N/A	X Walk 1 Width (in)	
3.3	X Walk 2 Slope (%)		1.0	X Walk 1 Slope (%)	
0.4	X Walk 2 X Slope (%)		0.2	X Walk 1 X Slope (%)	
N/A	Ramp inside XWalk2?	N/A	N/A	Ramp inside XWalk1?	N/A
N/A	Clear Space?		2.7	Road Slope (%)	
N/A	Clear Space to XWalk (in)	N/A	0.2	Road X Slope (%)	
N/A	Storm Grate/Utility Hazard?	N/A	N/A	Any Obstructions?	N/A
	Storm Grate/Utility Type			Obstruction Type	
N/A			N/A		
Good	Surface Condition? (G/P)	Yes			
2.9	Curb Slope (%)	N/A		A CONTRACTOR OF THE PARTY OF TH	
					-



Stop Condition-Street 2



