

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A


Good

Surface Condition? (G/P)

Intersection ID: 32290Main Street:CLEMENTINE\_CTCross Street:STEWARTS\_BEND\_LNLocation:SEADA ID: C86B390838AFRamp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:10

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

CLEMENTINE CT
StopSign
STEWARTS BEND LN
None

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Total Cost: \$ 3200.00

ricia measarements/ouriponent compnance						
	Compli	Compliance Description		Compli	ance Description	Data
	N/A	Ramp Length (in)	44.0	Yes	Ramp Slope (%)	6.1
	No	Ramp Width (in)	43.0	No	Ramp XSlope (%)	4.3
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	N/A	Shared Landing?	N/A			
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To N		X Walk 2 Direction	To W
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	7.0		X Walk 2 Slope (%)	2.0
		X Walk 1 X Slope (%)	2.5		X Walk 2 X Slope (%)	4.8
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	3.6	N/A	Clear Space?	N/A
		Road X Slope (%)	5.0	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type			Storm Grate/Utility Type	





