

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Good

Surface Condition? (G/P)

ADA ID: C913091D91B4 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

E W T HARRIS BV Signal N SHARON AMITY RD Signal Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

| Field Measurements/Component Compilance |                       |       |      |                             |       |
|---|-----------------------|-------|------|-----------------------------|-------|
| Compliance Description                  |                       | Data  | Comp | liance Description          | Data  |
| N/A                                     | Ramp Length (in)      | 59.5  | No   | Ramp Slope (%)              | 8.6   |
| Yes                                     | Ramp Width (in)       | 48.0  | No   | Ramp XSlope (%)             | 2.1   |
| N/A                                     | Flare Type LT         | N/A   | N/A  | Flare Type RT               | N/A   |
| N/A                                     | Flare Slope LT (%)    | N/A   | N/A  | Flare Slope RT (%)          | N/A   |
| N/A                                     | Flare Traversable LT? | N/A   | N/A  | Flare Traversable RT?       | N/A   |
| N/A                                     | Landing Length (in)   | N/A   | N/A  | DWS Provided?               | N/A   |
| N/A                                     | Landing Width (in)    | N/A   | N/A  | DWS Contrast?               | N/A   |
| N/A                                     | Landing Slope (%)     | N/A   | N/A  | DWS Length (in)             | N/A   |
| N/A                                     | Landing X Slope (%)   | N/A   | N/A  | DWS Full Width?             | N/A   |
| N/A                                     | Landing Curb? (Y/N)   | N/A   | N/A  | DWS Offset (in)             | N/A   |
| N/A                                     | Shared Landing?       | N/A   |      |                             |       |
| N/A                                     | Gutter Ponding?       | N/A   | N/A  | Gutter Slope (%)            | N/A   |
| N/A                                     | Gutter Lip Ht (in)    | N/A   | N/A  | Gutter X Slope (%)          | N/A   |
| N/A                                     | Painted X Walk1?      | No    | N/A  | Painted X Walk2?            | Yes   |
|   | X Walk 1 Direction    | To SW |      | X Walk 2 Direction          | To SE |
| N/A                                     | X Walk 1 Width (in)   | N/A   | N/A  | X Walk 2 Width (in)         | 117.0 |
|   | X Walk 1 Slope (%)    | 3.2   |      | X Walk 2 Slope (%)          | 1.6   |
|   | X Walk 1 X Slope (%)  | 2.8   |      | X Walk 2 X Slope (%)        | 0.4   |
| N/A                                     | Ramp inside XWalk1?   | N/A   | N/A  | Ramp inside XWalk2?         | Yes   |
|   | Road Slope (%)        | 0.7   | N/A  | Clear Space?                | N/A   |
|   | Road X Slope (%)      | 2.2   | N/A  | Clear Space to XWalk (in)   | N/A   |
| N/A                                     | Any Obstructions?     | N/A   | N/A  | Storm Grate/Utility Hazard? | N/A   |
|   | Obstruction Type      |       |      | Storm Grate/Utility Type    |       |





