

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 48312 Main Street: ROCKY\_BROOK\_CT Cross Street: TRILLIUM\_FIELDS\_DR Location: SE

ADA ID: C9BA7258A50B Ramp Type: Perp Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 0.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name TRILLIUM FIELDS DR
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

<u> </u>	Possible Solution	
	Possible Solutions:	Con
	Remove & Replace Entire Ramp.	N/A
i.	•	Yes
		N/A
Photo:		N/A
1		N/A
		No
	Surveyor Notes:	Yes
	N/A	Yes
3		Yes
		N/A
Š		N/A
	PROW/ADA:	Yes
	R304.5.3, R304.2.1, R305.2	Yes
d		N/A
1		N/A
		N/A





Total Cost:



1850.00

Compliance Description		Data	Compliance		Description	Data
N/A	Ramp Length (in)	47.0	Yes	Ramp	Slope (%)	5.1
Yes	Ramp Width (in)	48.0	No	Ramp	XSlope (%)	4.5
N/A	Flare Type LT	Sloped	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	9.0	N/A	Flare	Slope RT (%)	2.2
N/A	Flare Traversable LT?	No	N/A	Flare	Traversable RT?	No
No	Landing Length (in)	47.5	Yes	DWS	Provided?	Yes
Yes	Landing Width (in)	48.0	Yes	DWS	Contrast?	Yes
Yes	Landing Slope (%)	1.9	Yes	DWS	Length (in)	24.0
Yes	Landing X Slope (%)	3.2	Yes	DWS	Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	No	DWS	Offset (in)	4.0
N/A	Shared Landing?	No				
Yes	Gutter Ponding?	No	Yes	Gutte	r Slope (%)	2.9
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutte	r X Slope (%)	2.9
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A
	X Walk 1 Direction	To W		X Wa	lk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	5.4		X Wa	lk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	3.5		X Wa	lk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear	Space?	Yes
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm	Grate/Utility Hazard?	No
	Obstruction Type			Storm	Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good