


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|-----------------------|----------------------|--------------------------|------------------------|
| Intersection ID: 8500 | Main Street: ERIE_ST | Cross Street: LASALLE_ST | Location: NW |
| ADA ID: C9F4409C861D | Ramp Type: PerpDiag | Initial Pass/Fail: Fail | Overall Compliance: No |
| | | | Severity Score: 31.25 |

| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | |
|---|---|--|---|--------------------------|-------------|
|  | Possible Solutions: | | Compliance | Description | Data |
| | Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. | | Compliance | Description | Data |
| <p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1, R304.2.2, R304.5.3</p> | | | No | Ramp Length (in) | 59.5 |
| | | | No | Ramp Width (in) | 34.0 |
| | | | N/A | Flare Type LT | N/A |
| | | | N/A | Flare Slope LT (%) | N/A |
| | | | N/A | Flare Traversable LT? | N/A |
| | | | N/A | Landing Length (in) | N/A |
| | | | N/A | Landing Width (in) | N/A |
| | | | N/A | Landing Slope (%) | N/A |
| | | | N/A | Landing X Slope (%) | N/A |
| | | | N/A | Landing Curb? (Y/N) | N/A |
| | | | N/A | Shared Landing? | N/A |
| | | | N/A | Gutter Ponding? | N/A |
| | | | N/A | Gutter Lip Ht (in) | N/A |
| | | | N/A | Painted X Walk1? | No |
| | | | | X Walk 1 Direction | To S |
| | | | N/A | X Walk 1 Width (in) | N/A |
| | | | | X Walk 1 Slope (%) | 8.6 |
| | | | | X Walk 1 X Slope (%) | 0.7 |
| | | | N/A | Ramp inside XWalk1? | N/A |
| | | | | Road Slope (%) | 3.6 |
| | | | | Road X Slope (%) | 5.5 |
| | | | N/A | Any Obstructions? | N/A |
| | | | | Obstruction Type | |
| | | | N/A | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |

Total Cost: \$ 3200.00

