

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10281Main Street: CAMPUS_STCross Street: DIXON_STLocation:SWADA ID: CA381BE9D9C2Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score:10

Codes/Mitigation Info/Possible Solution



Street 1 Name DIXON ST
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

| Possible Solution | |
|-------------------------------|------|
| Possible Solutions: | Comp |
| Remove & Replace Entire Ramp. | N/A |
| | No |
| | N/A |
| | N/A |
| | N/A |
| | N/A |
| Surveyor Notes: | N/A |
| N/A | N/A |
| | N/A |
| | N/A |
| | N/A |
| PROW/ADA: | N/A |
| R304.5.1, R304.5.3 | N/A |
| | N/A |
| | N/A |
| | N/A |





Total Cost:



1850.00

| u33/1 | an. ran Overan | Compilan | icc. it | o deventy ocore. | | |
|---|-----------------------|----------|---------|-----------------------------|------|--|
| Field Measurements/Component Compliance | | | | | | |
| Comp | liance Description | Data | Comp | liance Description | Data | |
| N/A | Ramp Length (in) | 54.0 | Yes | Ramp Slope (%) | 7.3 | |
| No | Ramp Width (in) | 46.0 | No | Ramp XSlope (%) | 3.0 | |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| N/A | Shared Landing? | N/A | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A | |
| | X Walk 1 Direction | To N | | X Walk 2 Direction | N/A | |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | |
| | X Walk 1 Slope (%) | 1.9 | | X Walk 2 Slope (%) | N/A | |
| | X Walk 1 X Slope (%) | 2.8 | | X Walk 2 X Slope (%) | N/A | |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| | Road Slope (%) | N/A | N/A | Clear Space? | N/A | |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A | |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | N/A | | | N/A | |
| | | | Yes | Surface Condition? (G/P) | Good | |