

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

7.1

0.2

N/A

Good

Main Street: COLONIAL_COUNTRY_LN **Cross Street: LUNDIN LINKS LN** Location: Intersection ID: 27874 NW Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No ADA ID: CAFF7873A2BE Severity Score:** 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Flare Type RT

N/A



COLONIAL COUNTRY LN Street 1 Name Stop Condition-Street 2 None N/A Street 2 Name Stop Condition-Street 1 N/A

FOSSIBLE SOLUTION		i ielu ivieasui t	511161113/6
Possible Solutions:	Comp	Compliance Description	
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	48.0
·	No	Ramp Width (in)	47.0
	N/A	Flare Type LT	N/A
	N/A	Flare Slope LT (%)	N/A
	N/A	Flare Traversable LT?	N/A
	N/A	Landing Length (in)	N/A
Surveyor Notes:	N/A	Landing Width (in)	N/A
N/A	N/A	Landing Slope (%)	N/A
	N/A	Landing X Slope (%)	N/A
	N/A	Landing Curb? (Y/N)	N/A
	N/A	Shared Landing?	N/A
PROW/ADA:	N/A	Gutter Ponding?	N/A
Not Found, R304.5.1	N/A	Gutter Lip Ht (in)	N/A
	N/A	Painted X Walk1?	No
		X Walk 1 Direction	To SE
	N/A	X Walk 1 Width (in)	N/A
		X Walk 1 Slope (%)	0.3
		X Walk 1 X Slope (%)	0.2
	N/A	Ramp inside XWalk1?	N/A
		Road Slope (%)	N/A
		Road X Slope (%)	N/A
	N/A	Any Obstructions?	N/A

1850.00





Total Cost:



Obstruction Type