

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 26572 Main Street: ARBORHILL RD **Cross Street: ELIZABETH GLEN DR** Location: ADA ID: CB600D435842 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 8.75

Codes/Mitigation Info/Possible Solution



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 **ELIZABETH GLEN DR** StopSign **ARBORHILL RD** None

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1

Total Cost: 3200.00

Field Measurements/Component Compliance							
	Comp	Compliance Description		Comp	iance Descripti	ion	Data
	N/A	Ramp Length (in)	49.5	Yes	Ramp Slope (%)	7.3
	No	Ramp Width (in)	38.0	Yes	Ramp XSlope (%)	0.8
	N/A	Flare Type LT	N/A	N/A	Flare Type RT		N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT	(%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversab	le RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	•	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?		N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in	1)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width	1?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	1	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%	o)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope	(%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted X Walk	2?	No
		X Walk 1 Direction	To NW		X Walk 2 Directi	ion	To SW
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width	(in)	N/A
		X Walk 1 Slope (%)	0.7		X Walk 2 Slope	(%)	1.7
		X Walk 1 X Slope (%)	0.6		X Walk 2 X Slop	oe (%)	1.6
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XV	Valk2?	N/A
		Road Slope (%)	1.7	N/A	Clear Space?		N/A
		Road X Slope (%)	0.4	N/A	Clear Space to	XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Uti	lity Hazard?	N/A
		Obstruction Type			Storm Grate/Uti	lity Type	
			N/A				N/A
				Yes	Surface Condition	on? (G/P)	Good





