

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Internection ID: 40552				<b>O1 1 1 1</b>		Leastien	05			
Intersection ID: 10553	Main Street: CHARLES_AV			Cross Street: PINCKNEY_AV				Location:	SE	
ADA ID: CCE1E2463B39	DA ID: CCE1E2463B39 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	Se sa m	Possible Solutions:		Compliance Description			Data Compliance Description			
	12 Mar	Remove & Replace Entire Ram	<b>)</b> .	N/A	Ramp Length (in)	66.0	No	Ramp Slope (%)	11.1	
				Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.1	
	35 80.0			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
Contraction of the second	A MARKED			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
A Particular in the second				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
CHARLES AV	The second	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
the second second		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	· ·			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
5 - 18				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	19			N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Sec.	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		·		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
					X Walk 1 Direction	To N		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name CHA	RLES AV				X Walk 1 Slope (%)	0.5		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.3		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good

