

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

7.6

1.6

N/A

Good

**Cross Street: VIZCAYA CT** Intersection ID: N/A Main Street: BISCAY DR Location: SE Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: D06649F0E63D Ramp Type: Perp **Severity Score:** 8.75

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

Yes

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

**DWS Provided?** 

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

102.0

45.0

N/A

No

To N

N/A

0.1

1.8

N/A

N/A

N/A

N/A

N/A

Road X Slope (%)

Any Obstructions?

**Obstruction Type** 



**BISCAY DR** Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solution		rieiu ivieas
Possible Solutions:	Comp	liance Description
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)
·	No	Ramp Width (in)
	N/A	Flare Type LT
	N/A	Flare Slope LT (%)
	N/A	Flare Traversable LT?
	N/A	Landing Length (in)
Surveyor Notes:	N/A	Landing Width (in)
N/A	N/A	Landing Slope (%)
	N/A	Landing X Slope (%)
	N/A	Landing Curb? (Y/N)
	N/A	Shared Landing?
PROW/ADA:	N/A	Gutter Ponding?
Not Found, R304.5.1	N/A	Gutter Lip Ht (in)
	N/A	Painted X Walk1?
		X Walk 1 Direction
	N/A	X Walk 1 Width (in)
		X Walk 1 Slope (%)
		X Walk 1 X Slope (%)
	N/A	Ramp inside XWalk1?
		Road Slope (%)





Total Cost:



N/A

1850.00