

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

12.0

| Main Street: ALBEMARLE_RD               |                           |   | Cross Street: THORN_GROVE_LN  |  |   |   |   | Location:   | SE  |
|---|---------------------------|---|---|--|---|---|---|---|---|
| Ramp Ty                                 | amp Type: Para            |   |   | Initial Pass/Fail: Fail Overall Compliance   |   |   |   | o Severity Score:   | 13.75   |
| Codes/Mitigation Info/Possible Solution |                           |   | Field Measurements/Component Compliance   |  |   |   |   |   |   |
| Mar Martin                              | Possible Solutions:       |   |   |  |   |   |   | Data  |   |
| 618                                     | Remove & Replace Entire I | Ramn  | •   |  |   | 51.5  | N/A   | Ramp Length RT (in)   | 57.0  |
|   |                           |   |   | Yes  | Ramp Width LT (in)  | 90.0  | Yes   | Ramp Width RT (in)  | 89.5  |
| -                                       |                           |   |   | No   | Ramp Slope LT (%)   | 8.5   | Yes   | Ramp Slope RT (%)   | 8.1   |
| 1                                       |                           |   |   | No   | Ramp XSlope LT (%)  | 2.6   | Yes   | Ramp XSlope RT (%)  | 0.4   |
| 1                                       |                           |   |   | N/A  |   | N/A   | N/A   | DWS Provided?   | N/A   |
| 5.1                                     |                           |   |   | N/A  | Landing Width (in)  | N/A   | N/A   | DWS Contrast?   | N/A   |
| - and                                   | Surveyor Notes:           |   |   | N/A  | Landing Slope (%)   | N/A   | N/A   | DWS Length (in)   | N/A   |
| Ch-                                     |                           |   |   | N/A  | Landing X Slope (%)   | N/A   | N/A   | DWS Full Width?   | N/A   |
| The                                     |                           |   |   | N/A  | Landing Curb? (Y/N)   | N/A   | N/A   | DWS Offset (in)   | N/A   |
| 0                                       |                           |   |   | N/A  | Shared Landing?   | N/A   |   |   |   |
| 1                                       |                           |   |   | N/A  | Gutter Ponding?   | N/A   | N/A   | Gutter Slope (%)  | N/A   |
| 3                                       | PROW/ADA:                 |   |   | N/A  | Gutter Lip Ht (in)  | N/A   | N/A   | Gutter X Slope (%)  | N/A   |
|   | R304.3.2. R304.5.3        |   |   | N/A  | Painted X Walk1?  | No  | N/A   | Painted X Walk2?  | N/A   |
|   | ,                         |   |   |  | X Walk 1 Direction  | To W  |   | X Walk 2 Direction  | N/A   |
| 10- C                                   |                           |   |   | N/A  | X Walk 1 Width (in)   | N/A   | N/A   | X Walk 2 Width (in)   | N/A   |
|   |                           |   |   |  | X Walk 1 Slope (%)  | 3.8   |   | X Walk 2 Slope (%)  | N/A   |
| OVE LN                                  |                           |   |   |  | X Walk 1 X Slope (%)  | 3.5   |   | X Walk 2 X Slope (%)  | N/A   |
| topSign                                 |                           |   |   | N/A  | Ramp inside XWalk1?   | N/A   | N/A   | Ramp inside XWalk2?   | N/A   |
| N/A                                     |                           |   |   |  | Road Slope (%)  | N/A   | N/A   | Clear Space?  | N/A   |
| N/A                                     |                           |   |   |  | Road X Slope (%)  | N/A   | N/A   | Clear Space to XWalk (in)   | N/A   |
|   |                           |   |   | N/A  | Any Obstructions?   | N/A   | N/A   | Storm Grate/Utility Hazard?   | N/A   |
|   |                           |   |   |  | Obstruction Type  |   |   | Storm Grate/Utility Type  |   |
|   | Total Cost:               | \$ 16   | 600.00  |  |   | N/A   |   |   | N/A   |
|   |                           |   |   |  |   |   | Yes   | Surface Condition? (G/P)  | Good  |
|   | Ramp Ty<br>ion Info/      | Ramp Type: Para     ion Info/Possible Solution     Possible Solutions:     Remove & Replace Entire     Surveyor Notes:     N/A     PROW/ADA:     R304.3.2, R304.5.3 | Aamp Type: Para<br>ion Info/Possible Solution<br>Possible Solutions:<br>Remove & Replace Entire Ramp.<br>Surveyor Notes:<br>N/A<br>PROW/ADA:<br>R304.3.2, R304.5.3<br>OVE LN<br>topSign<br>N/A<br>N/A | Ramp Type: Para   Initial Pa     ion Info/Possible Solutions:   Possible Solutions:     Remove & Replace Entire Ramp.   Initial Pa     Surveyor Notes:   N/A     N/A   PROW/ADA:     R304.3.2, R304.5.3   Initial Pa | Ramp Type:   Para   Initial Pass/Fa     ion Info/Possible Solutions:   Compl     Remove & Replace Entire Ramp.   N/A     Yes   No     No   No     No   No     No   No     N/A   N/A     Surveyor Notes:   N/A     N/A   N/A     PROW/ADA:   N/A     R304.3.2, R304.5.3   N/A     OVE LN   N/A     N/A   N/A     N/A   N/A     N/A   N/A | Ramp Type:   Para   Initial Pass/Fail:   Fail   Overall     ion Info/Possible Solution   Field Measure   Field Measure   Field Measure     Possible Solutions:   Remove & Replace Entire Ramp.   N/A   Ramp Length LT (in)   Yes     Remove & Replace Entire Ramp.   N/A   Ramp Length LT (in)   Yes   Ramp Width LT (in)     No   Ramp XSlope LT (%)   No   Ramp XSlope LT (%)   N/A   Landing Length (in)     Surveyor Notes:   N/A   Landing Slope (%)   N/A   Landing Slope (%)     N/A   N/A   Landing Curb? (Y/N)   N/A   Shared Landing?     PROW/ADA:   N/A   Gutter Ponding?   N/A   Gutter Lip Ht (in)     R304.3.2, R304.5.3   N/A   Painted X Walk1?   X Walk 1 Direction     N/A   N/A   Ramp inside XWalk1?   X Walk 1 Slope (%)     N/A   N/A   Ramp inside XWalk1?   Road Slope (%)     N/A   N/A   Ramp inside XWalk1?   Road Slope (%)     N/A   Any Obstructions?   Obstruction Type | Ramp Type:   Para   Initial Pass/Fail:   Fail   Overall Compliant     ion Info/Possible Solution   Field Measurements/C     Possible Solutions:   Compliance Description   Data     Remove & Replace Entire Ramp.   N/A   Ramp Length LT (in)   51.5     Yes   Ramp Width LT (in)   90.0   No   Ramp Stope LT (%)   8.5     No   Ramp Stope LT (%)   2.6   N/A   Landing Length (in)   N/A     Surveyor Notes:   N/A   Landing Stope (%)   N/A   N/A   Landing Stope (%)   N/A     N/A   Landing Stope (%)   N/A   N/A   Landing Stope (%)   N/A     N/A   N/A   Landing Stope (%)   N/A   N/A   N/A   Stope (%)   N/A     N/A   N/A   N/A   Landing Curb? (Y/N)   N/A   N/A   N/A   N/A   N/A   N/A   Stope (%)   N/A     N/A   R304.3.2, R304.5.3   N/A   Qutter Lip Ht (in)   N/A   X Walk 1 Stope (%)   3.8     OVE LN   KopSign   N/A   Ramp inside XWalk1?   N/A   Road Stope (%)   N/A | Ramp Type: Para Initial Pass/Fail: Fail Overall Compliance: N   ion Info/Possible Solutions: Field Measurements/Compo Data Compliance Description Data Compliance   Remove & Replace Entire Ramp. N/A Ramp Length LT (in) 51.5 N/A   No Ramp Slope LT (%) 8.5 Yes   N/A Landing Length (in) N/A N/A   Surveyor Notes: N/A Landing Slope (%) N/A   N/A Landing Slope (%) N/A N/A   N/A Landing X Slope (%) N/A N/A   N/A Landing Slope (%) N/A N/A   N/A Surveyor Notes: N/A Landing Slope (%) N/A   N/A Randed Landing? N/A N/A   N/A Gutter Lip Ht (in) N/A N/A   N/A Gutter Lip Ht (in) N/A N/A   R304.3.2, R304.5.3 N/A Painted X Walk1? No   N/A N/A Ramp inside XWalk1? N/A   N/A Ramp inside XWalk1? N/A   N/A Road Slope (%) N/A   N/A Rande (%) N/A   N/A Rande (%) N/A   N | Ramp Type: Para Initial Pass/Fail: Overall Compliance: No Severity Score:   ion Info/Possible Solution: Field Measurements/Component Compliance Description Data Description   Possible Solutions: Remove & Replace Entire Ramp. N/A Ramp Length LT (in) 51.5 N/A Ramp Length RT (in)   Yes Ramp Width LT (in) 51.5 N/A Ramp Length RT (in) Yes Ramp Width RT (in)   Yes Ramp Slope LT (%) 8.5 Yes Ramp Slope RT (%) N/A N/A DWS Provided?   Surveyor Notes: N/A Landing Slope (%) N/A N/A DWS Forvided?   N/A Landing Cutr? (Y/N) N/A N/A DWS Forvided?   N/A Rading Cutr? (Y/N) N/A N/A DWS Forvide?   N/A Rading Cutr? (Y/N) N/A N/A DWS Forvide?   N/A Rading Cutr? (Y/N) N/A N/A |

