

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 32115	Main Street: COLE_MILL_RD			Street:	GALTY_LN	Location:	E		
ADA ID: D34EF40C6DA3	Ramp Ty	Ramp Type: BlendTrans1			ail: Fail Overall (o Severity Score:	12.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:					Comp	ompliance Description Data	
1999		Remove & Replace Curb Ramp V	With	N/A	Ramp Length (in)	48.0	Yes	BlendTrans Slope (%)	4.7
		Two New Directional Ramps or		Yes	Ramp Width (in)		No	BlendTrans XSlope (%)	6.9
	./// _3.	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A
	1 James 1			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	1/2	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
PROW/ADA: Not Found, R304.5.3				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	COLE MILL RD	•			X Walk 1 Slope (%)	6.8		X Walk 2 Slope (%)	3.8
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	0.0 0.9		X Walk 2 X Slope (%)	3.8 3.9
Street 2 Name	GALTY LN			N/A	Ramp inside XWalk1?	0.9 N/A	N/A	Ramp inside XWalk2?	3.9 N/A
				N/A	•		N/A	•	
Stop Condition-Street 2	StopSign				Road Slope (%)	0.9		Clear Space?	N/A
					Road X Slope (%)	5.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

5.7