

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.5

7.9

N/A

No

N/A

0.9

5.1

N/A

N/A

N/A

N/A

N/A

Good

To NE

Intersection ID: 50705Main Street:HARMONIOUS_STCross Street:GENERATIONS_STLocation:NWADA ID: D36E06E78448Ramp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:37.5

Compliance Description

Ramp Length (in)

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Compliance Description

Ramp Slope (%)

<u>Data</u>

49.0



Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes: N/A

Possible Solutions:

PROW/ADA:

R304.2.2, R304.5.3

Street 1 Name HARMONIOUS ST
Stop Condition-Street 2 None
Street 2 Name GENERATIONS ST
Stop Condition-Street 1 StopSign

No Ramp XSlope (%) Yes Ramp Width (in) 48.0 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A Flare Slope RT (%) Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A DWS Provided? Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? No N/A Painted X Walk2? X Walk 1 Direction To SE X Walk 2 Direction N/A N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) X Walk 1 Slope (%) X Walk 2 Slope (%) 7.4 X Walk 1 X Slope (%) 4.2 X Walk 2 X Slope (%) N/A N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? Road Slope (%) 9.6 N/A Clear Space? N/A Road X Slope (%) 7.4 Clear Space to XWalk (in) N/A N/A Any Obstructions? N/A Storm Grate/Utility Hazard? **Obstruction Type** Storm Grate/Utility Type

N/A

Yes

Surface Condition? (G/P)





Total Cost:



3200.00