

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10039534 Main Street: THATCHER\_HALL\_CT Cross Street: N/A Location: SE

ADA ID: D54E5776F774 Ramp Type: BlendTrans1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

**Codes/Mitigation Info/Possible Solution** 



Street 1 Name THATCHER HALL CT
Stop Condition-Street 1 None
Street 2 Name N/A
Stop Condition-Street 2 N/A

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

Not Found, R304.5.1

	Total
COLE	



Cost:



3200.00

Field Measurements/Component Compliance						
Comp	liance Description	Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	46.0	Yes	BlendTrans Slope (%)	4.9	
No	Ramp Width (in)	36.0	Yes	BlendTrans XSlope (%)	1.8	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To N		X Walk 2 Direction	N/A	
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	3.9		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	3.9		Clear Space?	N/A	
	Road X Slope (%)	2.6	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	
			No	Curb Slope (%)	7.6	