

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

9.4

Intersection ID: 12427	Main Street: W_STONEWALL_ST				Cross Street: S_MINT_ST				Location: S		
ADA ID: D5973C7AD996	Ramp Type: Para				Initial Pass/Fail: Fail Overall Compliance					22.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description Data			Compliance Description Data			
	Pro Maria	Remove & Replace Entire	Rar	np.	N/A	Ramp Length LT (in)	108.0	N/A	Ramp Length RT (in)	61.0	
				•	No	Ramp Width LT (in)	44.0	Yes	Ramp Width RT (in)	65.0	
6	100				No	Ramp Slope LT (%)	9.9	No	Ramp Slope RT (%)	N/A	
					No	Ramp XSlope LT (%)	4.2	No	Ramp XSlope RT (%)	N/A	
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
A A A A A A A A A A A A A A A A A A A					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		Surveyor Notes:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	2	N/A			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	1	-			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
Participant and	Ka				N/A	Shared Landing?	N/A				
And Frank	120				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
HAR BUTTE	1110	PROW/ADA:			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
P As P	t here	R304.5.1, R304.3.2, R304.	5.3		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
Salar I Make March	14 1					X Walk 1 Direction	To N		X Walk 2 Direction	N/A	
	- 7/2				N/A	X Walk 1 Width (in)	102.0	N/A	X Walk 2 Width (in)	N/A	
The second second	1. Second					X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	N/A	
Street 1 Name	S MINT ST					X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	N/A	
Stop Condition-Street 1	YieldSign				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Street 2 Name	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
Stop Condition-Street 2	N/A					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
						Obstruction Type			Storm Grate/Utility Type		
		Total Cost:	\$	1600.00			N/A			N/A	
								Yes	Surface Condition? (G/P)	Good	

