

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14251 Main Street: CHESTERFIELD AV **Cross Street: LORNA_ST** Location: N

ADA ID: D5F9DCE09055 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5

Codes/Mitigation Info/Possible Solution



CHESTERFIELD AV Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name **LORNA ST** Stop Condition-Street 1 None Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2





Total Cost:



3200.00

Field Measurements/Component Compliance						
Compliance Description		Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	62.0	No	Ramp	Slope (%)	8.7
Yes	Ramp Width (in)	87.0	Yes	Ramp	XSlope (%)	0.4
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	Yes	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	No
	X Walk 1 Direction	To SW		X Wa	lk 2 Direction	To SE
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	ılk 2 Width (in)	N/A
	X Walk 1 Slope (%)	5.0		X Wa	lk 2 Slope (%)	3.9
	X Walk 1 X Slope (%)	1.2		X Wa	lk 2 X Slope (%)	0.5
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	o inside XWalk2?	N/A
	Road Slope (%)	0.5	N/A	Clear	Space?	N/A
	Road X Slope (%)	3.6	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type			Storn	n Grate/Utility Type	
		N/A				N/A

Yes

Surface Condition? (G/P)

Good