

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



		-			-					
Intersection ID: 10040584	Main Street: W_ARROWOOD_RD				Street:	N/A	Location:	NW		
ADA ID: D6A51C3110A4	Ramp Ty	amp Type: Directional1				itial Pass/Fail: Pass Overall Compliance: No				10
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description			Data Compliance Description		
		Remove & Replace Ent	ire Ran	np.	N/A	Ramp Length (in)	69.0	No	Grade Break?	No
17 . · · · · · · · · · · · · · · · · · ·					Yes	Ramp Width (in)	61.0	N/A	Grade Break Slope (%)	5.8
	7				Yes	Ramp Slope (%)	7.2	N/A	Grade Break XSlope (%)	5.0
	e -	1			Yes	Ramp XSlope (%)	0.4			
and Manager	1/0-1				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
Tesher , 194					N/A	Flare Slope LT (%)	9.2	Yes	Flare Slope RT (%)	4.2
		Surveyor Notes:			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	Yes
the second se	State.	N/A			Yes	Landing Length (in)	59.0	No	DWS Provided?	No
the second secon					Yes	Landing Width (in)	60.0	N/A	DWS Contrast?	No
W ARRON	Contraction of the second				No	Landing Slope (%)	6.5	N/A	DWS Length (in)	N/A
WOOD RD	-				Yes	Landing X Slope (%)	1.2	N/A	DWS Full Width?	No
A CONTRACTOR OF THE OWNER OF THE	and the second	PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	Not Found, R304.2.2-Perp, R304.3			N/A	Shared Landing?	No	N/A	DWS Offset RT (in)	N/A	
New Contraction of the Contracti	1	Para, R304.5.2, R305			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.4
TEE STATE STATE					Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.3
TTTTTT AND AND A MARKEN					N/A	Painted X Walk1?	No		Road Slope (%)	3.4
Street 1 Name	ENTRANCE					X Walk 1 Direction	To E		Road X Slope (%)	1.3
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A		Clear Space?	Yes
Street 2 Name	N/A					X Walk 1 Slope (%)	3.4	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	1.3	Yes	Storm Grate/Utility Hazard?	No
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
					Yes	Any Obstructions?	No			N/A
		Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
							N/A	No	Curb Slope (%)	15.5

