cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 47909	ID: 47909 Main Street: MOUNTAIN_QUAIL_DR Cross Street: HARRIER_RD						Location:	w
ADA ID: D986D9048946				nitial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	31.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:						liance Description	Data
	Remove & Replace C	urb Ramp With	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	11.9
	Two New Directional I		No	Ramp Width (in)	35.0	No	Ramp XSlope (%)	2.6
	Equivalent.	•	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	Star.		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
E Mailar			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
E the	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
C. C.	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
6. B			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	and the second s	No.	N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1,	R304.2.2.	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	R304.5.3	, ,	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To NE		X Walk 2 Direction	To SE
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	HARRIER RD			X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	0.6
Stop Condition-Street 2	StopSign			X Walk 1 X Slope (%)	4.2		X Walk 2 X Slope (%)	2.1
Street 2 Name MOUNTA	IN QUAIL DR		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None			Road Slope (%)	3.2	N/A	Clear Space?	N/A
				Road X Slope (%)	5.7	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost:	\$ 3200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

s Surface Condition? (G/P)

Good

