


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 16684	Main Street: SELWYN_FARMS_LN	Cross Street: SELWYN_OAKS_CT	Location: SW
ADA ID: D9A2E72BC12F	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 10	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		Yes	Ramp Length (in)	37.0
			No	Ramp Width (in)	47.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			No	Painted X Walk1?	N/A
			To E	X Walk 1 Direction	N/A
			N/A	X Walk 1 Width (in)	N/A
			5.8	X Walk 1 Slope (%)	N/A
			2.5	X Walk 1 X Slope (%)	N/A
			N/A	Ramp inside XWalk1?	N/A
Surveyor Notes: N/A PROW/ADA: R304.5.1, R304.5.3			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Gutter Slope (%)	N/A
			N/A	Gutter X Slope (%)	N/A
			No	Painted X Walk2?	N/A
			To N	X Walk 2 Direction	N/A
			N/A	X Walk 2 Width (in)	N/A
			2.6	X Walk 2 Slope (%)	N/A
			2.9	X Walk 2 X Slope (%)	N/A
			N/A	Ramp inside XWalk2?	N/A
			N/A	Clear Space?	N/A
			N/A	Clear Space to XWalk (in)	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Storm Grate/Utility Type	N/A
			N/A	Surface Condition? (G/P)	Good
Total Cost:		\$ 3200.00			

Street 1 Name	SELWYN FARMS LN
Stop Condition-Street 2	None
Street 2 Name	SELWYN OAKS CT
Stop Condition-Street 1	StopSign

