cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| · · · · · · · · · · · · · · · · · · · | | | | | | | | | |
|---|--------------------------------|--|---------------------------|--|--------|-----|-----------------------------|------|--|
| Intersection ID: N/A | N/A Main Street: TRYON_ST | | Cross Street: ANANDALE_DR | | | | Location: | NE | |
| ADA ID: D9B16C3651AE | B16C3651AE Ramp Type: PerpDiag | | Initial Pass/F | itial Pass/Fail: Pass Overall Compliance: No | | | o Severity Score: | 20 | |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| | | Possible Solutions: | | Compliance Description Data | | | Compliance Description Data | | |
| | | Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter. | th N/A | Ramp Length (in) | 90.0 | Yes | Ramp Slope (%) | 5.5 | |
| | | | Yes | Ramp Width (in) | 48.0 | Yes | Ramp XSlope (%) | 1.9 | |
| | | | N/A | Flare Type LT | Sloped | N/A | Flare Type RT | N/A | |
| | | | N/A | Flare Slope LT (%) | 9.3 | N/A | Flare Slope RT (%) | 1.6 | |
| | | | N/A | Flare Traversable LT? | Yes | N/A | Flare Traversable RT? | No | |
| | | | No | Landing Length (in) | N/A | No | DWS Provided? | No | |
| | | Surveyor Notes: | No | Landing Width (in) | N/A | N/A | DWS Contrast? | No | |
| | | N/A | No | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| | and they are | | No | Landing X Slope (%) | N/A | N/A | DWS Full Width? | No | |
| A 0 0 A | NANDAUR | | N/A | Landing Curb? (Y/N) | No | N/A | DWS Offset (in) | N/A | |
| | Contrad Col | | N/A | Shared Landing? | No | | | | |
| L. L. | | PROW/ADA: | Yes | Gutter Ponding? | No | Yes | Gutter Slope (%) | 0.1 | |
| BAR I Bay whe | With more " | R304.2.1, R304.2.2-Perp, R304.3.2- | Yes | Gutter Lip Ht (in) | 0.0 | No | Gutter X Slope (%) | 2.8 | |
| BUT IN | | Para, R304.5.3, R305 | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No | |
| | | ,, | | X Walk 1 Direction | To W | | X Walk 2 Direction | To S | |
| and I have a sub- | E TIME | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | |
| Street 1 Name | S TRYON ST | • | | X Walk 1 Slope (%) | 1.2 | | X Walk 2 Slope (%) | 5.7 | |
| Stop Condition-Street 2 | None | | | X Walk 1 X Slope (%) | 2.2 | | X Walk 2 X Slope (%) | 4.4 | |
| Street 2 Name | ANANDALE DR | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| Stop Condition-Street 1 | StopSign | | | Road Slope (%) | 0.1 | N/A | Clear Space? | Yes | |
| | . • 5 | | | Road X Slope (%) | 2.8 | N/A | Clear Space to XWalk (in) | N/A | |
| | | | Yes | Any Obstructions? | No | Yes | Storm Grate/Utility Hazard? | No | |
| | | Total Cost: \$ 395 | 50.00 | Obstruction Type | | | Storm Grate/Utility Type | - | |
| | | | | 51 | N/A | | | N/A | |
| | | | | | | Yes | Surface Condition? (G/P) | Good | |
| | | | | | | • | | | |

