## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

6.1

Intersection ID: 29638	Main Street: COLONY_RD			Street:	SUMMERLIN_PL	Location:	W		
ADA ID: D9E8821C18BB	Ramp T	Ramp Type: ParaDiag			Initial Pass/Fail: Fail Overall Compliance: No				13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	9	Possible Solutions:		Compliance Description Dat			a Compliance Description Data		
		Remove & Replace Curb Ra	mp With	N/A	Ramp Length LT (in)	36.0	N/A	Ramp Length RT (in)	40.0
		Two New Directional Ramps	•	Yes	Ramp Width LT (in)	101.0	Yes	Ramp Width RT (in)	102.0
		Equivalent.		No	Ramp Slope LT (%)	8.4	Yes	Ramp Slope RT (%)	6.1
				No	Ramp XSlope LT (%)	3.9	Yes	Ramp XSlope RT (%)	0.0
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		Surveyor Notes:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
The second second				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		PROW/ADA:		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		R304.3.2, R304.5.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
		4			X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	3.4
Street 1 Name	SUMMERLIN PL	-			X Walk 1 X Slope (%)	2.5		X Walk 2 X Slope (%)	1.6
Stop Condition-Street 1	StopSign			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	COLONY RD				Road Slope (%)	1.6	N/A	Clear Space?	N/A
Stop Condition-Street 2	None				Road X Slope (%)	4.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type			Storm Grate/Utility Type	
		Total Cost: \$	3200.00			N/A			N/A
							Yes	Surface Condition? (G/P)	Good

