## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



|  |   |            |  |                       |      |                             | Location                    | SW    |
|--|---|------------|--|-----------------------|------|-----------------------------|-----------------------------|-------|
|  | Main Street: BRADWELL_DR                    |            | Cross Street: LANGHAM_CT                       |                       |      |                             | Location:                   |       |
| ADA ID: DA456E977DFD Ramp Type: PerpDiag   |   | Initial Pa | Initial Pass/Fail: Fail Overall Compliance: No |                       |      |                             | o Severity Score:           | 21.25 |
| Codes/Mitigation Info/Possible Solution  |   |            | Field Measurements/Component Compliance        |                       |      |                             |                             |       |
| Enclosed a la constant de | Possible Solutions:                         |            | Compliance Description                         |                       |      | Data Compliance Description |                             |       |
|  | Remove & Replace Curb Ramp W                | /ith       | N/A  | Ramp Length (in)      | 48.0 | Yes                         | Ramp Slope (%)              | 5.4   |
|  | Two New Directional Ramps or<br>Equivalent. |            | No   | Ramp Width (in)       | 36.0 | No                          | Ramp XSlope (%)             | 6.7   |
|  |   |            | N/A  | Flare Type LT         | N/A  | N/A                         | Flare Type RT               | N/A   |
|  |   |            | N/A  | Flare Slope LT (%)    | N/A  | N/A                         | Flare Slope RT (%)          | N/A   |
|  |   |            | N/A  | Flare Traversable LT? | N/A  | N/A                         | Flare Traversable RT?       | N/A   |
|  |   |            | N/A  | Landing Length (in)   | N/A  | N/A                         | DWS Provided?               | N/A   |
|  | Surveyor Notes:                             |            | N/A  | Landing Width (in)    | N/A  | N/A                         | DWS Contrast?               | N/A   |
|  | N/A   |            | N/A  | Landing Slope (%)     | N/A  | N/A                         | DWS Length (in)             | N/A   |
|  |   |            | N/A  | Landing X Slope (%)   | N/A  | N/A                         | DWS Full Width?             | N/A   |
|  |   |            | N/A  | Landing Curb? (Y/N)   | N/A  | N/A                         | DWS Offset (in)             | N/A   |
|  |   |            | N/A  | Shared Landing?       | N/A  |                             |                             |       |
|  | PROW/ADA:                                   |            | N/A  | Gutter Ponding?       | N/A  | N/A                         | Gutter Slope (%)            | N/A   |
|  | Not Found, R304.5.1, R304.5.3               |            | N/A  | Gutter Lip Ht (in)    | N/A  | N/A                         | Gutter X Slope (%)          | N/A   |
|  |   |            | N/A  | Painted X Walk1?      | No   | N/A                         | Painted X Walk2?            | No    |
|  |   |            |  | X Walk 1 Direction    | To E |                             | X Walk 2 Direction          | To N  |
|  |   |            | N/A  | X Walk 1 Width (in)   | N/A  | N/A                         | X Walk 2 Width (in)         | N/A   |
| Street 1 Name LANGHAM CT   |   |            |  | X Walk 1 Slope (%)    | 2.2  |                             | X Walk 2 Slope (%)          | 1.6   |
| Stop Condition-Street 2 StopSign   |   |            |  | X Walk 1 X Slope (%)  | 2.4  |                             | X Walk 2 X Slope (%)        | 2.8   |
| Street 2 Name BRADWELL DR  |   |            | N/A  | Ramp inside XWalk1?   | N/A  | N/A                         | Ramp inside XWalk2?         | N/A   |
| Stop Condition-Street 1 None   |   |            |  | Road Slope (%)        | 3.7  | N/A                         | Clear Space?                | N/A   |
|  |   |            |  | Road X Slope (%)      | 1.6  | N/A                         | Clear Space to XWalk (in)   | N/A   |
|  |   |            | N/A  | Any Obstructions?     | N/A  | N/A                         | Storm Grate/Utility Hazard? | N/A   |
|  | Total Cost: \$ 32                           | 200.00     |  | Obstruction Type      |      |                             | Storm Grate/Utility Type    |       |
|  |   |            |  |                       | N/A  |                             |                             | N/A   |

Yes Surface Condition? (G/P)

Good

