

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 53633Main Street: TREMONT\_RIDGE\_CTCross Street: BEACON\_VALLEY\_STLocation: NWADA ID: DC3A503A1998Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name BECON VALLEY ST
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions: N/A Remove & Replace Entire Ramp. Yes N/A N/A N/A N/A Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: Not Found, R304.5.3

N/A
N/A
N/A
N/A
N/A
N/A
N/A
1850.00

Compliance Description Data Compliance Description Data Yes Ramp Length (in) 95.0 Ramp Slope (%) 5.9 No Ramp XSlope (%) Ramp Width (in) 48.0 9.6 N/A Flare Type LT N/A Flare Type RT N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A **DWS Provided?** N/A Landing Length (in) Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? Gutter Ponding? N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? No N/A Painted X Walk2? N/A X Walk 1 Direction To SE X Walk 2 Direction N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) X Walk 2 Slope (%) N/A 3.4 X Walk 1 X Slope (%) 9.6 X Walk 2 X Slope (%) N/A N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? N/A Road Slope (%) N/A N/A Clear Space? N/A N/A Road X Slope (%) N/A Clear Space to XWalk (in) N/A N/A Any Obstructions? N/A Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good





Total Cost:

