

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

| | | | • | | - | | | | | |
|---|---|-----------------|------------------|---|---------------------|-----------------------|-------------------|---------------------|-----------------------------|-----|
| Intersection ID: 23801 | n ID: 23801 Main Street: STEPHENDALE_DR | | | | Street: | S_TRYON_ST | Location: | SE | | |
| ADA ID: DCFA61830418 | DA ID: DCFA61830418 Ramp Type: MedianPerp | | | | ass/Fa | ail: Fail Overall (| o Severity Score: | 22.5 | | |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | | |
| Possible Solutions: | | | | | | | | liance Description | Data | |
| | 11. | Remove & Replac | o Entiro Ramo | | N/A | Ramp Length (in) | 84.0 | | Ramp Slope (%) | 8.7 |
| | | Remove a Replac | | | No | Ramp Width (in) | 44.0 | | Ramp XSlope (%) | 2.8 |
| | | | | | N/A | Flare Type LT | N/A | | Flare Type RT | N/A |
| | | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | V. 19. | | | | N/A | Flare Traversable LT? | N/A | | Flare Traversable RT? | N/A |
| | | | | | N/A | Landing Length (in) | N/A | | DWS Provided? | N/A |
| | ALL AND AND A | Surveyor Notes: | | | N/A | Landing Width (in) | N/A | | DWS Contrast? | N/A |
| | | N/A | | | N/A | Landing Slope (%) | | N/A | DWS Length (in) | N/A |
| | 10/4 | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| 6. William State | | | | | N/A | Landing Curb? (Y/N) | N/A | | DWS Offset (in) | N/A |
| | | | | | N/A | Shared Landing? | N/A | | | |
| the state | Contraction of the second | PROW/ADA: | | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| Not Found, R304.5.1, F R304.5.3 | | | 51 R304 2 2 | | N/A | Gutter Lip Ht (in) | N/A | | Gutter X Slope (%) | N/A |
| | | | .0.1, 1(004.2.2, | | N/A | Painted X Walk1? | No | | Painted X Walk2? | N/A |
| | | | | | | X Walk 1 Direction | To NE | | X Walk 2 Direction | N/A |
| and the second second | | | | N/A | X Walk 1 Width (in) | | N/A | X Walk 2 Width (in) | N/A | |
| Street 1 Name | STEPHENDALE DR | • | | | | X Walk 1 Slope (%) | 4.0 | | X Walk 2 Slope (%) | N/A |
| Stop Condition-Street 2 | StopSign | | | | | X Walk 1 X Slope (%) | 6.6 | | X Walk 2 X Slope (%) | N/A |
| Street 2 Name | N/A | | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | N/A | | | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | | | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: | \$ 1 | 650.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | | N/A | | | N/A |
| | | | | | | | | | | |

