


Intersection ID: 12811	Main Street: SCHOOL_ST	Cross Street: THOMAS_AV	Location:	NW
ADA ID: DD02F150FC33	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 8.75

Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Possible Solutions:			Compliance	Description	Data	Compliance	Description	Data
	<b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b>			N/A	Ramp Length (in)	36.0	Yes	Ramp Slope (%)	5.4
				No	Ramp Width (in)	43.0	Yes	Ramp XSlope (%)	0.8
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	Surveyor Notes:			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A				Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
PROW/ADA: <b>Not Found, R304.5.1</b>			N/A	Shared Landing?	N/A				
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
			N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A	
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
				X Walk 1 Direction	To S		X Walk 2 Direction	To E	
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
				X Walk 1 Slope (%)	8.3		X Walk 2 Slope (%)	6.7	
				X Walk 1 X Slope (%)	4.8		X Walk 2 X Slope (%)	3.6	
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
				Road Slope (%)	1.6	N/A	Clear Space?	N/A	
Total Cost: \$ 3200.00				Road X Slope (%)	8.7	N/A	Clear Space to XWalk (in)	N/A	
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
				Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A	
						Yes	Surface Condition? (G/P)	Good	
Street 1 Name			SCHOOL ST						
Stop Condition-Street 2			StopSign						
Street 2 Name			THOMAS AV						
Stop Condition-Street 1			StopSign						

