## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

|   |                   | ٩  | <u> </u>               | <u> </u>                                |   |               |                             |                             |                |
|---|-------------------|--|------------------------|---|---|---------------|-----------------------------|-----------------------------|----------------|
| Intersection ID: 18436                  | Main Str          | eet: E_INDEPENDENCE_BV                     | Cross St               | Cross Street: SHARON_FOREST_DR          |   |               |                             | Location:                   | NE             |
| ADA ID: DE39475D4269                    | Ramp Ty           | Ramp Type: PerpDiag                        |                        |   | Initial Pass/Fail: Fail Overall Compliance: |               |                             | o Severity Score:           | 22.5           |
| Codes/Mitigation Info/Possible Solution |                   |  |                        | Field Measurements/Component Compliance |   |               |                             |                             |                |
|   |                   | Possible Solutions:                        | Compliance Description |   |   | Data          | Data Compliance Description |                             |                |
|   |                   | Remove & Replace Curb Ramp V               | /ith                   | N/A                                     | Ramp Length (in)                            | 66.0          | No                          | Ramp Slope (%)              | 11.8           |
|   | All               | Two New Directional Ramps or               |                        | No                                      | Ramp Width (in)                             | 45.0          | No                          | Ramp XSlope (%)             | 2.7            |
| the the                                 |                   | Equivalent.                                |                        | N/A                                     | Flare Type LT                               | N/A           | N/A                         | Flare Type RT               | N/A            |
|   | S. 6/ 24          |  |                        | N/A                                     | Flare Slope LT (%)                          | N/A           | N/A                         | Flare Slope RT (%)          | N/A            |
|   | Star of           |  |                        | N/A                                     | Flare Traversable LT?                       | N/A           | N/A                         | Flare Traversable RT?       | N/A            |
|   |                   | Surveyor Notes:                            |                        | N/A                                     | Landing Length (in)                         | N/A           | N/A                         | DWS Provided?               | N/A            |
|   |                   |  |                        | N/A                                     | Landing Width (in)                          | N/A           | N/A                         | DWS Contrast?               | N/A            |
|   |                   | N/A  |                        | N/A                                     | Landing Slope (%)                           | N/A           | N/A                         | DWS Length (in)             | N/A            |
|   |                   |  |                        | N/A                                     | Landing X Slope (%)                         | N/A           | N/A                         | DWS Full Width?             | N/A            |
|   |                   |  |                        | N/A                                     | Landing Curb? (Y/N)                         | N/A           | N/A                         | DWS Offset (in)             | N/A            |
| No sol                                  | K. ANTA           |  |                        | N/A                                     | Shared Landing?                             | N/A           |                             | 2                           |                |
| A AND                                   | autor The         | PROW/ADA:                                  |                        | N/A                                     | Gutter Ponding?                             | N/A           | N/A                         | Gutter Slope (%)            | N/A            |
| munn                                    |                   |  |                        | N/A                                     | Gutter Lip Ht (in)                          | N/A           | N/A                         | Gutter X Slope (%)          | N/A            |
| 5. Jul                                  |                   | Not Found, R304.5.1, R304.2.2,<br>R304.5.3 |                        | N/A                                     | Painted X Walk1?                            | No            | N/A                         | Painted X Walk2?            | Yes            |
|   | 1                 | K304.3.3                                   |                        | IN/A                                    | X Walk 1 Direction                          | To SW         | N/A                         | X Walk 2 Direction          | To SE          |
| 6                                       |                   |  |                        | N/A                                     |   | 10 SVV<br>N/A | N/A                         |                             | 10 SE<br>120.0 |
|   |                   |  |                        | N/A                                     | X Walk 1 Width (in)                         |               | N/A                         | X Walk 2 Width (in)         |                |
| Street 1 Name                           | E INDEPENDENCE BV |  |                        |   | X Walk 1 Slope (%)                          | 4.1           |                             | X Walk 2 Slope (%)          | 1.4            |
| Stop Condition-Street 2                 | Signal            |  |                        |   | X Walk 1 X Slope (%)                        | 0.4           |                             | X Walk 2 X Slope (%)        | 3.1            |
| Street 2 Name                           | SHARON FOREST DR  |  |                        | N/A                                     | Ramp inside XWalk1?                         | N/A           | N/A                         | Ramp inside XWalk2?         | Yes            |
| Stop Condition-Street 1                 | Signal            |  |                        |   | Road Slope (%)                              | 2.4           | N/A                         | Clear Space?                | N/A            |
|   |                   |  |                        |   | Road X Slope (%)                            | 2.5           | N/A                         | Clear Space to XWalk (in)   | N/A            |
|   |                   |  |                        | N/A                                     | Any Obstructions?                           | N/A           | N/A                         | Storm Grate/Utility Hazard? | N/A            |
|   |                   | Total Cost: \$ 32                          | 200.00                 |   | Obstruction Type                            |               |                             | Storm Grate/Utility Type    |                |
|   |                   |  |                        |   |   | N/A           |                             |                             | N/A            |

