

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 28277	reaction ID: 28277 Main Streat: EASTON CREVIN				PEMSWOOD_ST	Location:	S			
		Main Street: EASTON_GREY_LN								
ADA ID: DE611BEC89A4	39A4 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
Sen a la sen	por ser	Possible Solutions:		Compliance Description			Data Compliance Description		Data	
A B	San Street	Remove & Replace Entire Ramp		N/A	Ramp Length (in)	95.0	No	Ramp Slope (%)	9.7	
	A Contraction			Yes	Ramp Width (in)	59.0	Yes	Ramp XSlope (%)	1.6	
To B				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
Her war		1		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
B.				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
K NOOD ST	The second when	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
PELLO	mar and all	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
attante to			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
1 2 3 2 2	pro- 1			N/A	Shared Landing?	N/A				
	The T	PROW/ADA:		N/A	Gutter Ponding?	Yes	N/A	Gutter Slope (%)	N/A	
Auto A Mark	Min T	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
the second se					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
	John Toll 1			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	PEMSWOOD ST				X Walk 1 Slope (%)	5.7		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

