

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| | | | • | <u> </u> | / | | | | | | | |
|--|-------------------------|-------------------------|----------------|--|------------------------------|---|---------------------------|-----------------------------|-----------------------------|------|--|--|
| Intersection ID: 8588 | Main Street: HYDE_DR | | | | Cross Street: W_CRAIGHEAD_RD | | | | Location: SE | | | |
| ADA ID: DEBA16243E5C | Ramp Type: Combination1 | | | Initial Pass/Fail: Fail Overall Complian | | | nce: No Severity Score: 1 | | 10 | | | |
| Codes/Mitigation Info/Possible Solution | | | | | | Field Measurements/Component Compliance | | | | | | |
| | F287 # 19 | Possible Solutions: | | Compliance Description | | | | Data Compliance Description | | | | |
| a state of the sta | 1 | Remove & Replac | e Entire Ramp | | N/A | Ramp Length LT (in) | 33.5 | | Ramp Length RT (in) | 33.5 | | |
| | | | | | Yes | Ramp Width LT (in) | 58.5 | Yes | Ramp Width RT (in) | 60.0 | | |
| | | | | Yes | Ramp Slope LT (%) | 8.3 | Yes | Ramp Slope RT (%) | 0.7 | | | |
| | | | | No | Ramp XSlope LT (%) | 2.8 | Yes | Ramp XSlope RT (%) | 1.3 | | | |
| A Mar No A | | | | | N/A | Ramp Length (in) | 48.0 | Yes | Ramp Slope (%) | 4.0 | | |
| UNDE DR & C | - | | | | No | Ramp Width (in) | 46.5 | Yes | Ramp XSlope (%) | 0.3 | | |
| | | Surveyor Notes: | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | | |
| | | GTR LIP 2.0, RT RP < 5% | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | | |
| | Mar I a | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | | |
| | Se the M | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | | |
| | 297 | | | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | | |
| | A PART | PROW/ADA: | | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | | |
| | | Not Found, R304 | .5.1, R304.5.3 | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | | |
| | A TRACE | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | | |
| | Mar al | | | | N/A | Shared Landing? | N/A | | | | | |
| | and Alar | | | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | | |
| Street 1 Name | StopSign | | | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | | |
| Stop Condition-Street 1 | HYDE DR | | | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A | | |
| Street 2 Name | N/A | | | | | X Walk 1 Direction | To N | | X Walk 2 Direction | N/A | | |
| Stop Condition-Street 2 | N/A | | | | | X Walk 1 Width (in) | N/A | | X Walk 2 Width (in) | N/A | | |
| | | | | | | X Walk 1 Slope (%) | 5.3 | | X Walk 2 Slope (%) | N/A | | |
| | | | | | | X Walk 1 X Slope (%) | 3.1 | | X Walk 2 X Slope (%) | N/A | | |
| | | Total Cost: | \$ 18 | 800.00 | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | | |
| | | | | | | Road Slope (%) | N/A | | Clear Space? | N/A | | |
| | | | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A | | |
| | | | | | - | | | N/A | Any Obstruction? | N/A | | |
| | | | | | | | | | Obstruction Type | | | |
| | | | | - | 1 | | | | | N/A | | |
| | | | | 1 | | | | N/A | Storm Grate/Utility Hazard? | N/A | | |
| | 5 | | | 1 | a destroy | | | | Storm Grate/Utility Type | | | |
| | * | -1-1- | | - | and the second | and the second | | | | N/A | | |

| | | 11/14 |
|-----|--------------------------|-------|
| Yes | Surface Condition? (G/P) | Good |
| | Curb Slope (%) | 8.4 |