cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11933	Main Str	Main Street: W_8TH_ST		treet:	N_TRYON_ST	Location:	w		
ADA ID: DF65B5540328	Ramp Ty	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Co		Compliance: No		o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:	Compliance Description		liance Description	Data	Comp	liance Description	Data
		Remove & Replace Curb Ramp W	'ith	N/A	Ramp Length (in)	96.0	Yes	Ramp Slope (%)	6.2
		Two New Directional Ramps or		No	Ramp Width (in)	46.0	Yes	Ramp XSlope (%)	1.9
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	12			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
A A A A A A A A A A A A A A A A A A A	1944	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the states of th	<u>6</u>	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A A A A A A A A A A A A A A A A A A A	the second			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	BILL			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A I AR	1 - Mar	•		N/A	Shared Landing?	N/A			
San I and a second	XX	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
The Sand	and				X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
The La Star				N/A	X Walk 1 Width (in)	108.0	N/A	X Walk 2 Width (in)	110.0
Street 1 Name	N TRYON ST	_			X Walk 1 Slope (%)	2.9		X Walk 2 Slope (%)	1.1
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	0.6
Street 2 Name	W 8TH ST			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes
Stop Condition-Street 1	Signal				Road Slope (%)	2.3	N/A	Clear Space?	N/A
	-				Road X Slope (%)	0.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	00.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good

