

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13228 Main Stu	Main Street: CENTRAL_AV		Cross Street: LANDIS AV				SW
			Initial Pass/Fail: Fail Overall Compliance: No			Location: Severity Score:	
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
Possible Solutions:		· · · · · ·					Data
		<u>0011</u> N/A	Ramp Length (in)		No	Ramp Slope (%)	14.3
	Remove & Replace Entire Ramp.	No	Ramp Width (in)		Yes	Ramp XSlope (%)	1.5
		N/A	Flare Type LT		N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A
		N/A	Flare Traversable LT?		N/A	Flare Traversable RT?	N/A
		N/A N/A			N/A N/A	DWS Provided?	N/A N/A
CENURAL_AV	Cumunum Natan		Landing Length (in)		N/A		
	Surveyor Notes:	N/A	Landing Width (in)			DWS Contrast?	N/A
G. G.	N/A	N/A	Landing Slope (%)		N/A	DWS Length (in)	N/A
		N/A	Landing X Slope (%)		N/A	DWS Full Width?	N/A
		N/A	Landing Curb? (Y/N)		N/A	DWS Offset (in)	N/A
		N/A	Shared Landing?	N/A			
The second s	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.2.2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
The All States and the second states		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
			X Walk 1 Direction	To E		X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name LANDIS AV			X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 None			X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A			Road Slope (%)	N/A	N/A	Clear Space?	N/A
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 1	850.00	Obstruction Type			Storm Grate/Utility Type	
	•		51	N/A			N/A

s Surface Condition? (G/P)

Good

