

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16735 Main Street: JAMESTON\_DR Cross Street: PRINCETON\_AV Location: SW

ADA ID: DFEB2DDB1FBF Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

JAMESTON DR StopSign PRINCETON AV None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

Field Measurements/Component Compliance							
	Compliance Description		Data	Compliance		Description	Data
	N/A	Ramp Length (in)	74.0	No	Ramp	Slope (%)	9.1
	Yes	Ramp Width (in)	48.0	No	Ramp	XSlope (%)	2.2
	N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	Yes
		X Walk 1 Direction	ТоЕ		X Wa	lk 2 Direction	To NE
	N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	121.0
		X Walk 1 Slope (%)	3.1		X Wa	lk 2 Slope (%)	7.2
		X Walk 1 X Slope (%)	7.7		X Wa	lk 2 X Slope (%)	5.2
	N/A	Ramp inside XWalk1?	N/A	N/A	Ram	o inside XWalk2?	Yes
		Road Slope (%)	1.4	N/A	Clear	Space?	N/A
		Road X Slope (%)	8.2	N/A	Clear	Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
		Obstruction Type			Storn	n Grate/Utility Type	
			N/A				N/A
				Yes	Surfa	ce Condition? (G/P)	Good





