


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10037053	Main Street: S_TRYON_ST	Cross Street: N/A	Location: SE
ADA ID: E025B737FA39	Ramp Type: ParaDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 26.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length LT (in)	61.0
			Yes	Ramp Width LT (in)	61.0
			No	Ramp Slope LT (%)	13.4
			Yes	Ramp XSlope LT (%)	0.5
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	2.0
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To NE
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	0.4
				X Walk 1 X Slope (%)	4.4
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	4.2
				Road X Slope (%)	3.3
			N/A	Any Obstructions?	N/A
				Obstruction Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	2.2
Surveyor Notes: MEDIAN ACROSS S TRYON ST, RT RP < 5% PROW/ADA: R304.3.2, R304.5.3					
Total Cost: \$ 3200.00					

Street 1 Name	ENTRANCE
Stop Condition-Street 1	StopSign
Street 2 Name	S TRYON ST
Stop Condition-Street 2	None

