

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23302 Main Street: COLONY_RD Cross Street: MORROWICK_RD Location: SE

ADA ID: E050CA48D054 Ramp Type: BlendTrans2 Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 2.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name

Stop Condition-Street 1

Signal
Street 2 Name

COLONY RD

Stop Condition-Street 2

Signal

Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:

N/A

PROW/ADA:
Not Found, R305.1.4

Total Cost: \$ 3200.00

Field Measurements/Component Compliance					
Compliance Description		Data	Compliance Description		Data
N/A	Ramp Length (in)	114.0	Yes	BlendTrans Slope (%)	2.0
Yes	Ramp Width (in)	53.0	Yes	BlendTrans XSlope (%)	1.8
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
N/A	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
N/A	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
N/A	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.0
N/A	Landing X Slope (%)	N/A	No	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	1.0
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.5
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	2.7
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
	X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
	X Walk 1 Width (in)	107.0		X Walk 2 Width (in)	113.0
	X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	4.8
	X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	4.4
Yes	Ramp inside XWalk1?	Yes	Yes	Ramp inside XWalk2?	Yes
	Road Slope (%)	2.9		Clear Space?	Yes
	Road X Slope (%)	6.4	Yes	Clear Space to XWalk (in)	112.0
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
7			No	Curb Slope (%)	6.8





