

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14139 Main	Main Street: S_TRYON_ST		Cross Street: W_TREMONT_AV			Location:	SW
ADA ID: E05C1122D23F Ramp Type: Perp		Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
	Possible Solutions:	Com	Compliance Description Data Compliance			liance Description	Data
	Remove & Replace Entire Ramp	. N/A	Ramp Length (in)	76.0	Yes	Ramp Slope (%)	6.2
		No	Ramp Width (in)	43.0	Yes	Ramp XSlope (%)	0.1
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
the second secon		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
W TIREMONT_AY		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
estation in the second se	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N/A	Shared Landing?	N/A			
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	1		X Walk 1 Direction	To E		X Walk 2 Direction	N/A
the state of the s		N/A	X Walk 1 Width (in)	104.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name S TRYON S	г		X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 Sign	l l		X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	N/A
Street 2 Name N/	A	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/	A		Road Slope (%)	N/A	N/A	Clear Space?	N/A
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	1850.00	Obstruction Type			Storm Grate/Utility Type	
				N/A			N/A

Yes Surface Condition? (G/P)

Good

