

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18050	Main St	Main Streets & TRYON ST			Cross Street: SOUTHAMPTON PD				NE	
Intersection ID: 18050		Main Street: S_TRYON_ST			Cross Street: SOUTHAMPTON_RD			Location:		
ADA ID: E0C7A4DA8D5C	Ramp T	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: I			o Severity Score:	1.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			Data Compliance Description		Data	
The second second	10	Remove & Replace Entire Ram	р.	N/A	Ramp Length (in)	60.0	N/A	Grade Break?	N/A	
Ch.	ALL ASS	-	-	Yes	Ramp Width (in)	72.0	N/A	Grade Break Slope (%)	0.0	
				Yes	Ramp Slope (%)	5.1	N/A	Grade Break XSlope (%)	0.0	
the states of th	THE S			No	Ramp XSlope (%)	4.0				
Noite 2				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
Silver	A The			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
a da	A white	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
o t	BERNE AN	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
	LE KO			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	AN MER	R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
The second states	and the read			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A		
			N/A	Painted X Walk1?	No		Road Slope (%)	2.8		
Street 1 Name SOUT	HAMPTON RD				X Walk 1 Direction	To SW		Road X Slope (%)	5.2	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	2.8	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	5.2	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	0.3	

