

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 32102	Main Street: BLUE_HERON_DR			Cross Street: CASTLE_PINE_CT				Location:	SW	
ADA ID: E2CCE2AF5F83	8 Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	1.25		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
Possible Solutions:			Compliance Description Data			Compliance Description Data				
China China		Remove & Replace Entire Ran	מו.	N/A	Ramp Length (in)	92.0	N/A	Grade Break?	N/A	
		······································	· P ·	Yes	Ramp Width (in)	58.0	N/A	Grade Break Slope (%)	0.0	
	Mot S			Yes	Ramp Slope (%)	2.4	N/A	Grade Break XSlope (%)	0.0	
A A A A A A A A A A A A A A A A A A A	1. X 1			No	Ramp XSlope (%)	3.6				
Line and the	EPINE			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
CROWS_NEST_LN	7025			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
	A Land	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
स् २ म	Mar -	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
	le deser			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
	No. 2 Mar			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
	the matrice			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
ALLAND AND A DOL	A STATE	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	13 00.	R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
	and the C			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A		
and the second sec	All and a lot of the			N/A	Painted X Walk1?	No		Road Slope (%)	1.9	
Street 1 Name CROW	/S NEST LN				X Walk 1 Direction	To NW		Road X Slope (%)	1.1	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	1.9	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.1	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	7.6	

